

	А	В	(	С	D
1	UNDO PIEZO CABLES AND FEED THROUGH PIEZO HOLE ON FASCIA MOUNT PIEZO THROUGH THE FRONT OF THE FASCIA WITH RED FIBRE WASHER BETWEEN PIEZO NUT AND ON THE BACK OF THE FASCIA		ORIENTATE THE FILTER OF THE NAND THE SOLENOID DRIVER	SCREW U DO NOT TO INDIC	JPPER NIPPLE IN LOOSE. SCREW ALL THE WAY IN CATE IT IS LOOSE 1 DCTITE 577 LOCTITE VURE ENP077
2		FIX FASCIA TO FASCIA MOUNT AND FIX IN PLACE WITH TORX SCREWS		KEEP IN BOX-	INCLUDED IN BOX
3	NOTE	E INCLUDE TORX SCREW DRIVER BIT IN WITH EACH ASSEMBLY (672483)	FIT RUBBER GROMMIT TO AND SCREW ON LOOSE		3
4	REV. DATE ECN	SION DESCRIPTION MODIF BY I CABLE 480222; P/N 480779 WAS 672374. TD B	ENWARE RESERVES THE RIGHT TO AMMEND PRODUCT SPECIFICATIONS AND DESIGNS WITHOUT NOTICE	This drawing is the property of Enware	Y FINISH:   13 SIZE- 4.4 SCALE- 1/3 SHEET: 3 OF 4

